

MONUMENT RECORD  
State of Indiana - County of Monroe

Section: 21

Township: 7 North


Range: 1 East

Corner ID: Polk M-13

**Monument Description & Remarks:** 3" Brass Disk on 3" tube 1ft above ground. Survey Sign 2ft above ground at pt. B

**References On File:** Raymond Graham survey, Section 19 T7N, R1E (1995), on file in Surveyor Office.

RECOVERY TIE DRAWING  
Field Book 39 Page No. 12




- A - 3" Brass Disk
- B - N 01° W 2.07' to Survey Sign on 4"x4"x4' wood post
- C - N 10° E 9.54' to Sign on 18" White Oak
- D - S 52° E 4.20' Sign on 72" Bifurcated Black Oak
- E - S 04° W 70.00' to 1/2" Iron Pipe with cap "GRAHAM"


Not To Scale  
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 56-2-2 of the Indiana Code; and the above data is given under my hand and seal this 21st day of March, 2007.

*Kevin P. Enright*



Administered by the Monroe County Surveyor Review Board



Date: 4-17-2007



N13 F.S. Monument T7N R1E Sections 15,16,21 and 22  
 Polk\_M13

Polk\_M12

M13 T7N R1E

View to the Northwest



Index No. N-13  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)  
GPO 806-924

T. 34 R. 16 Mer. N.F. Kearney County Nebraska State Nebraska  
Corner common to sections 13, 16, 21 and 22

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Wood Post  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees  
Species chestnut Hickory  
Diameter 15" 12"  
Bearing N 28 W S 22 W  
Distance 10 1/2 12 1/2

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Where filed or recorded \_\_\_\_\_  
Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found


Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_



Sketch

○ Corner    ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,  
etc.

3. Man hours spent in search 1 hr.

4. Do you think additional search might  
recover evidence? Yes ☐ No ☒

5. Signature A. Beaton

# Relation of Evidence to Record Features Along Section Lines

|                          |       |       |       |       |
|--------------------------|-------|-------|-------|-------|
| Section line to sections | _____ | _____ | _____ | _____ |
| Object                   | _____ | _____ | _____ | _____ |
| Record distance          | _____ | _____ | _____ | _____ |
| Measured distance        | _____ | _____ | _____ | _____ |

## Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

## Perpetuation Record

Monument and accessories established. Include brief description of area.

Certified corner restoration certificate prepared: Yes ☐ No ☐

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_